PROJECT : SPACE TAFT

LOCATION : 1952 TAFT AVE., MALATE, MANILA

OWNER : PACIFIC AVELEX SUBJECT : PROGRESS REPORT

DATE : 07-Apr-16

STRUCTURAL WORKS

A. <u>PILE DRIVING</u>

-100% completed

B. <u>FOUNDATION</u>

PILE CAP

-100% completed

C. STP

97% COMPLETED STRUCTURAL WORKS





D. <u>CISTERN TANK</u>

97% COMPLETED STRUCTURAL WORKS



E. Column and Shearwall

99% COMPLETED (CONCRETED UP TO ROOFDECK FLOOR LEVEL)





F. Beams and Girders

99% COMPLETED (CONCRETED UP TO ROOFDECK FLOOR LEVEL)





G. Slab

98% COMPLETED





H. Main Stairs

50% completed (1st to 15th floor level)



I. Fire Exit Stairs

60% completed (3rd to 21st floor)



ARCHITECTURAL WORKS

A. Masonry Works

Floor Level

- a Ground floor
- **b** Mezzanine floor
- c 2nd floor
- **d** 3rd floor
- e 4th floor
- f 5th floor
- g 6th floor
- h 7th floor
- i 8th floor
- **j** 9th floor
- k 10th floorl 11th floor











(Interior & Exterior walls)

% Accomplishment

67.00	%

90.00 %

92.00 %

92.00 %

100.00 %

100.00 %

98.00 %

98.00 %

97.00 %

98.00 %

98.00 % 97.00 %

m	12th floor	98.00	%
n	13th floor	74.00	%
0	14th floor	92.00	%
р	15th floor	94.00	%
q	16th floor	92.00	%
r	17th floor	94.00	%
s	18th floor	92.00	%
t	19th floor	94.00	%
u	20th floor	63.00	%
V	21st floor	57.00	%
w	22nd floor	53.00	%
x	23rd floor	34.00	%
у	24th floor	26.00	%
Z	25th floor	34.00	%
a.a	26th floor	34.00	%
a.b	27th floor	4.00	%
a.c	28th floor	4.00	%
a.d	29th floor (additional-penthouse)	4.00	%

Note:

Exterior walls -up to 26th floor Interior walls -up to 22th floor

Masonry Pictures:







B. Ceiling Works at Hallway

Floor Level	% Accomplishment
mez. Floor	40%
4th floor	100%
5th floor	95%
6th floor	95%
7th floor	95%
8th floor	95%
9th floor	95%









B.a Cladding of Hallway Pipe Chase

Floor Level	% Accomplishment
4th floor	100%
5th floor	100%
6th floor	100%
7th floor	100%
8th floor	100%
9th floor	95%
10th floor	100%





B.b Cladding of Modular Toilet

Floor Level	% Accomplishment
4th floor	100%
5th floor	100%
6th floor	100%
7th floor	95%
8th floor	70%





C. <u>Installation of Door Jambs at Units</u>

341/490 door jamb installed (69%)





D. <u>Installation of Unit Doors and RFID Locksets</u>

79/490 units installed (16%)





E. <u>Installation of louver Doors at EE room</u>

26/26 units installed (100%)





F. Modular Toilets

100/490 units installed (20%)





G. Painting Works

Interior Painting

Floor Level	% Accomplishment
4th floor	100%
5th floor	95%
6th floor	95%
7th floor	95%
8th floor	85%
9th floor	50%
10th floor	0%
11th floor	15%









H. Floor Finishing Works

Hallway Floor Tiles

Floor Level	% Accomplishment
4th floor	98%
5th floor	95%
6th floor	95%
7th floor	95%
8th floor	95%
9th floor	95%
10th floor	95%
11th floor	95%
12th floor	90%
13th floor	0%
14th floor	70%
15th floor	70%
16th floor	70%
17th floor	70%
18th floor	20%

Unit Vinyl Tiles Floor Level

Unit Vinyl Tiles	
Floor Level	% Accomplishment
4th floor	100%
5th floor	100%
6th floor	100%









H. Installation of Unit Windows

164/490 units installed 33% completed







ELECTRICAL WORKS

CAL WORKS		
A. Roughing-ins	% Accomp	olishment
1 Lighting System	90.00	%
2 Convenience Outlet System	85.00	%
3 Power Feeder Lines	90.00	%
4 Panelboards/Circuit Breakers/ MC's	55.00	%
5 CCTV System	90.00	%
6 CATV System	90.00	%
7 Telephone System	90.00	%
8 Fire Alarm System	90.00	%
9 Lightning Protection System	90.00	%
10 Grounding System	90.00	%
B. Wiring		
1 Lighting System	45.00	%
2 Convenience Outlet System	45.00	%
3 Power Feeder Lines	45.00	%
4 CCTV System	45.00	%
5 CATV System	45.00	%
6 Telephone System	45.00	%
7 Fire Alarm System	45.00	%
8 Lightning Protection System	-	%
9 Grounding System	-	%
C. OWNERS SUPPLIED ITEMS (Installation Only)		
1 Wiring Devices for Lighting System	-	%
2 Wiring Devices for Conv. Outlets	-	%
3 Wiring Devices for CATV	-	%
4 Wiring Devices for Telephone	-	%
5 Panelboards and Circuit Breakers	40.00	%
6 Busway Equipments	-	%
7 Fire Alarm Equipments	-	%
8 Lighting Fixtures	5.00	%
9 Lightning Protection Equipment	-	%







Modular Toilet Lighting





Swimming Pool Lightings



9F Room Electrical Installation











4F to 15F Meter Center & Wiring Installation at Electrical Room



4th floor to 15th Floor - Circuit Breaker & Wire Installation at Rooms



PLUMBING AND SANITARY WORKS

A. UPDATED PROGRESS ACCOMPLISHMENT REPORT

OFD	ATED FROUNESS ACCOMPL	ISHIVILINI INLEGINI	
NO.	FLOORS	PLUMBING WORKS	FIRE PROTECTION WORKS
1	GROUND FLOOR	77%	45%
2	MEZZANINE FLOOR	90%	90%
3	SECOND FLOOR	90%	90%
4	THIRD FLOOR	90%	90%
5	FOURTH FLOOR	93%	90%
6	FIFTH FLOOR	96%	90%
7	SIXTH FLOOR	96%	90%
8	SEVENTH FLOOR	90%	90%
9	EIGHT FLOOR	85%	85%
10	NINTH FLOOR	70%	80%
11	TENTH FLOOR	70%	65%
12	ELEVENTH FLOOR	70%	65%
13	TWELVE FLOOR	70%	65%
14	THIRTEEN FLOOR	70%	65%
15	FOURTEEN FLOOR	70%	65%
16	FIFTEEN FLOOR	70%	65%
17	SIXTEEN FLOOR	32%	55%
18	SEVENTEEN FLOOR	32%	55%
19	EIGHTEEN FLOOR	32%	55%
20	NINETEEN FLOOR	32%	55%
21	TWENTY FLOOR	32%	55%
22	TWENTY ONE FLOOR	32%	55%
23	TWENTY TWO FLOOR	32%	10%
24	TWENTY THREE FLOOR	3%	10%
25	TWENTY FOURTH FLOOR	3%	10%
26	TWENTY FIFTH FLOOR	3%	10%
27	TWENTY SIXTH FLOOR	3%	10%
28	TWENTY SEVENTH FLOOR	3%	10%
29	TWENTY EIGHT FLOOR	3%	10%
30	TWENTY NINETH FLOOR	3%	10%
31	ROOF DECK FLOOR	0%	0%
	Accomplishment	46%	51%

a Pipe laying for Storm drain, Water line and Sanitary line, Air-con drain, Fire Protection pipe at Ground Floor.



b Parking Drain Line







c Main Sewrer Line







d Storm Drain Line And Water Line





e Swimming Pool Pumps and Drain Line







f Kitchenette and Modular Toilet







g Fire Protection, ITC and Auxiliary Drain Line










h Hydro Test/Leak Testing















2. Sanitary Line







3. Air Con Drain Line











4. Fire Protection Line

MECHANICAL WORKS:

Installation of ELEVATOR

<u>Unit</u> % Accomplishment

Elevator 1 62% Elevator 2 80% Elevator 3 90%





PERSPECTIVE VIEW:







Prepared by:
(ORIGINAL SIGNED)

Engr. Warren Sierra/Engr. Gabriel Tapel EJAP Konstruct Inc.-P.E. (C.E./M.E.P.F.)

Construction Management-Space Taft